



# WESTWIND YACHT SALES

Victoria Harbour (Georgian Bay), Ontario

Contact: Brenda Flower

Tel: (705) 528-9979

Email: [westwind@csolve.net](mailto:westwind@csolve.net)

[www.WestwindYachtsCanada.com](http://www.WestwindYachtsCanada.com)

## 1990 Neptunus 45 Sedan (Neptunus 138)


**\$178,500**



LOA	46' 2"	Beam	14' 0"
Draft	3' 9"	Displacement	14 Tons
Fuel	352 gals (1,600L)	Water gals	132 (600 L)
Power	T-Caterpillar 3208, 425hp, ~ 150 hours (Both engines completely rebuilt 2021/2022)		

### Sedan Style, Two-Staterooms, Two Heads, Cockpit

A very rare find! This Neptunus 138 owner has spent over \$90,000 refitting this vessel, including the completely rebuilt engines! The lower helm has been removed to make more room in the guest cabin and the guest cabin has been remodeled to increase space, light and fresh air flow. List of upgrades is attached!



### Accommodations

**Forward Master Stateroom:** Centerline berth, hanging lockers, overhead hatch.

**Guest Stateroom:** Twin berths w/storage under the beds, shelved locker, remodeled with overhead hatch on the ceiling to provide light and improve air flow.

**Salon:** Starboard side U-shaped seating w/storage under, new portside storage cabinets and countertops, new wall coverings, new Fusion stereo system and speakers, Black Novakool fridge/freezer 12v/120v. Custom Hunter Douglas window blinds.

**Cockpit/Platform:** transom door, 2 bench seats w/storage under, sliding door to salon, large in-floor lazarette w/ample storage, 5' swim platform with boarding ladder, canvas enclosure (excellent condition).

**Fly Bridge:** 2 Pedestal seats, passenger L-shaped seating w/table and storage under, canvas enclosure (excellent condition).

### Galley

Novakool Refrigerator/freezer 12v/120

Dinette with storage under

New 2 burner induction cooktop (portable or installed)

All details are believed to be correct, but not guaranteed by owner or Broker. Some information may have been sourced from manufacturer's brochures. It is the Purchaser's responsibility to have all engines, systems and integrity of the vessel inspected. **Page 1 of 2**

## **Electronics/Navigation Aids**

New Raymarine 9" touchscreen chartplotter (\$2,500)  
Raymarine radar – digital, linked to chartplotter  
Raymarine autopilot  
Raymarine depth sounder (to chartplotter or stand-alone)  
Raymarine knot meter  
Raymarine VHF Radio w/DSC  
Rudder angle indicator (as is)  
Wind direction and speed  
Starlink Satellite system

## **Equipment**

Westerbeke 11kW diesel generator (~ 905 hours)  
Victron Multiplus 3000 watt inverter  
Batteries - 2 x Lithium for partial house & inverter  
    - 2 x 8D for partial house  
    - 2 x 8D for starting  
    - 1 x 12v Genny  
ProMariner ProNautic 24.30P 30 Amp charger  
3 Air/reverse heat (all refurbished by Northland Supply)  
Windlass (refurbished) w/CQR anchor (all chain)

New solar panels (4 x 100w) mounted on radar arch  
Pressure cold & hot water  
New hot water heater w/heat exchanger system  
New hot water heater expansion tank  
New water filtration system – filters lake water  
Freshwater tank  
Dockside water inlet  
New transom shower – hot & cold  
Heads (2) – 1 accessible from the guest cabin  
Waste tank monitor  
Dual 30 amp shore power inlets & 30 amp Cords (2)  
CO detectors  
New electric heads (2)  
Dyson vacuum  
Marine BBQ w/pedestal on platform  
Sun pad cushions  
New Fusion stereo system w/salon & cockpit speakers  
All existing safety and mooring equipment

## **Retrofit Summary**

**Note:** Actual value of some of the upgrades listed below is far greater than shown below because where possible, the very qualified owner did some of the work himself.

Both Caterpillar 3208 engines rebuilt (2021/2022)	
Westerbeke generator removed and full maintenance performed	~ \$50,000
Generator oil pan removed for inspection and cleaning	
New plumbing throughout and new water heater (6 gal)	
All sanitation hoses replaced	\$ 3,000
New water filtration system that draws and filters water from the lake	\$ 1,000
New electric toilets (2)	
Removed the lower helm to make more room in the guest cabin	
Remodeled the guest cabin to increase space and fresh air flow	
Installed an internal hatch on the ceiling of the guest cabin to significantly improve light and fresh air flow	\$ 500
Lithium house battery system (2024)	\$ 3,500
New drive shafts and cutlass bearings and propellers balanced (2024/2025) - Insurance deductible	\$ 3,000
New Raymarine 9" touchscreen chartplotter	\$ 2,500
Starlink satellite system	\$ 750
Refurbished all 3 Air/Heat units – units were removed and sent to Northland Supply	\$ 1,500
Air/Heat units reinstalled spring 2025 by Northland Supply	\$ 1,800
Epoxy painted the entire engine room and replaced insulation (while engines and generator were out)	\$ 1,000
Removed, rebuilt and remounted the bowsprit. The core was replaced w/water impervious Coosa board	\$ 500
Epoxy painted the entire superstructure of the boat	\$ 3,000
Installed SeaDek decking on the swim platform, cockpit and bow area	\$ 3,500
Installed marine vinyl carpet in the salon	\$ 2,500
Installed vinyl flooring – Teak walnut combo in the galley	\$ 2,500
Epoxied the hull with 5 coats of epoxy and then applied high quality anti fouling paint (2023)	\$ 3,000
Refurbished the steering system – replaced all components with new stainless steel fixtures	
Installed 4 solar panels in a custom aluminum solar tray fixed to the radar arch	\$ 1,500
New commercial grade fabric wall coverings and walnut woodwork in the salon	\$ 2,500
New custom kitchen cabinet sink and faucet in the galley	\$ 1,000
Custom made cherry steps to the galley with hinged system for extra storage	\$ 300
New faucets in both heads	
Removed, cleaned, repainted and re-caulked all the windows (absolutely no leaks)	
Replaced all lights with LED	\$ 750
Installed new electrical panels – 12 volt/24volt and 110 AC (required with removal of the lower helm)	
New Fusion stereo system with new speakers in the salon and cockpit	\$ 1,000
	<b><u>\$89,050</u></b>

All details are believed to be correct, but not guaranteed by owner or Broker. Some information may have been sourced from manufacturer's brochures. It is the Purchaser's responsibility to have all engines, systems and integrity of the vessel inspected. **Page 2 of 2**